	er ID 65342 1 11:45:00 AM											Page
tem ID: Revision ID:	D3272-1			Accept					Setup			
tem Name:	Step									Stop		
Start Date:	1/12/11 Start Qty	: 6.00			Cust Item I	D:						
Required Date:	1/26/11 Req'd Qt	y: 6.00			Customer:							
Reference:												
Approvals:	Process Plan:	Da	te: 11/01/12	Tooling:	Da	ate:	_		Run	Start		
	QC:		te:	SPC (Y/N):		ate:				Stop		
Sequence ID/ Work Center II	Operation Description			Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	t Rej Qty	•	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr											
D3272	Rev B											
00	Large Fab	Memo		0.00	. Hi			6		B_		
arge Fab			END BEFORE CU	TTING OTHER END***	M 11	· 0/ ·	20		,			
		1-Cut D2622-120 (table setup DT 818		long as per Dwg D3272 u	using cutting							
	:	2-Drill extrusion as	per Dwg D3272 usi	ing Jig DT8680 for rivets								
		3-Deburr										

110

Quality Control

QC6- Inspect dimensions to drawing

Memo

W/O:			WC	ORK ORDER CHANGI	ES								
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng /	Approval QC Inspector				
								Prod Mgr					
													
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _					
	R	esolution:	Dispositio	n:	_ QA: N/C CI	osed:		Date: _					
NCR:		,	WORK ORDER NON-CONFORMANCE (NCR)										
DATE	STEP Description of NC			Corrective Action Section		Verifi	cation	Approval	Approval				
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		tion C	Chief Eng	QC Inspector				
								i					
					ļ			}					
				•									
		·											

Work Order ID 65342

January 12, 2011 11:45:00 AM



Page 2

Item ID:

D3272-1

Accept

Setup Start



Revision ID:

Start Date:

Item Name: Step

Required Date: 1/26/11

1/12/11

Start Qty: 6.00

Req'd Qty: 6.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____

Date:

Tooling:

Date:

Start

Stop



Date: _____

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop



Sequence ID/ **Work Center ID**

120



Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location: 111A

0.00

Tool ID

Tool # Plan

Accept Qty

Reject Reject Qty Number

Insp. Stamp

Memo

0.00

Code

Run

130

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

	-								
W/O:			WO	RK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						11 11 11 11	-		
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date:	·····
	Re	esolution:	Disposition	:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector
				¥.					
					. ,	!			
				The state of the s					

Picklist Print

January 12, 2011 11:44:59 AM

Work Order ID: 65342

Parent Item:

D3272-1

Parent Item Name: Step



Start Date: 1/12/11

Required Date: 1/26/11

Start Qty: 6.00

Required Qty: 6.00

Comments:

IPP Rev:A

New Issue 07-06-09

Manufactured

JLM

No

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Primary Bin Item Location Last Location

Route Seq ID

100

Unit of

Each

Qty on Measure Hand

9.7000

Loc Code

Qty per Kit Total Qty

Qty Issued Date Status

Issued

D2622-120C

Step Extrusion

Location

WA

58544

61208

Loc Qty 9.7 3.42

1 5.28

W/O:	<u> </u>		\M\O	DV ODDED CHANC	EC				
W/O:				RK ORDER CHANG				Approval Chief Eng /	Approval
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Chief Eng / Prod Mgr	QC Inspector
								in .	
					1				
 -							<u> </u>		1
Part No		PAR #:							
	Re	esolution:	Disposition	n:	_ QA: N/C C	osed:		Date: _	
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (NCF	₹)			
DATE	OTED	Description of NC			ion B	Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	& Sect	ion C	Chief Eng	QC Inspector
						:			
								-	
					ļ	ļ			
								1	



	_			
DESIG	P	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAI	
CHECK	ED	APPROVED	DRAWING NO.	REV. B
(世	D3272	SHEET 1 OF 3
DATE			TITLE	SCALE
07.0	5.18		STEP ASSEMBLY, HI LONG	NTS
Α		04.03.01	NEW ISSUE	
В		07.05.18	D3272-1 WAS D2622-120	

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3 BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.

SHOP COPY RETURN TO **ENGINEERING** UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER NO. 65342

CX11/01/12

Duit Au	Ospace	Liu							. Æ .
W/O:			WO	RK ORDER CHANGES					·
DATE	STEP	PRO	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No		PAR #:	Fault Categ	jory: No	CR: Yes I	No DQ	A:	_ Date: _	
	R	esolution:	Disposition	ı: Q.	A: N/C Clo	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMANC	E (NCR)			
		Description of NC		Corrective Action Section B		Verification		Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	tion C	Chief Eng	QC Inspector
								į.	



D3272

EEEE SEEE

N


읶

DRAWING NO

HAWKESBURY,

AEROSPACE I

DETAIL A



- 116.25

(CUT LENGTH OF D3272-1, REF)

봀

DOCUMENT IS

Copyright © 2004 by DART AEROSPACE PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM

NOT TO BE USED I

ĘŖ

₹

PURPOSE OR


COPIED

Dart Aerospace Ltd	D	art	Aer	osi	pace	Ltd
--------------------	---	-----	-----	-----	------	-----

W/O:			wc	RK ORDER CHAN	GES				
DATE	STEP	PRO	OCEDURE CHA		Ву	Date	Qty	Approval Chief Eng /	Approval QC Inspector
-								Prod Mgr	QC Inspector
							<u> </u>		
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	_ Date: _	
	Re	esolution:	Dispositio	n:	QA: N/C C	osed:		Date: _	
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE (NCF	R)			
		Description of NC		Corrective Action Se	ection B	Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	n Sign a	k Sec	tion C	Chief Eng	QC Inspector
			:			į			
VE. J. II									
									}
	-								



į	DESIGN	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CA	
	CHECKED	APPROVED	DRAWING NO. D3272	REV. B SHEET 3 OF 3
	DATE		TITLE	SCALE
	07.05.18		STEP ASSEMBLY, HI LONG	1:20



	•								
W/O:			WC	ORK ORDER CHANGE	S				
DATE	STEP	PROC	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Dort No.	-	PAR #:	Foult Coto		NCP: Voc	No DO	۸-	Date:	
Part NO		solution:							
NCR:		W	ORK ORDI	ER NON-CONFORMA	NCE (NCF	R)			
		Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector
·····									-
· 									